

# **OSBORN** SAFETY DATA SHEET

Date Issued- 1/1/2024

SDS no. BA-609

	555 NO. DA 005
1. PRODUCT AND COMP	ANY IDENTIFICATION
PRODUCT DESCRIPTION	D-32
CHEMICAL NAME	Blended abrasive solid
GENERAL USE	Polish for metal finishing
MANUFACTURER ADDRESS	Osborn
	3440 Symmes Rd. Hamilton
	OH 45015 USA
CONTACT NUMBER	1-513-860-3400
EMERGENCY CONTACT	PLANT OPERATIONS
EMERGENCY PHONE	1-513-678-3672
24 HOUR EMERGENCY	
TELEPHONE NUMBER	CHEMTREC (24 HOURS) 800-424-9300
2. HAZARD IDENTIFICAT	ION
EMERGENCY OVERVIEW	
IMMEDIATE CONCERNS	Danger! Contains silica. Dust from buffing operation may cause
	damage to the lungs. May also irritate the eyes and the skin. Protective
	equipment should be worn. Wash skin after use.
POTENTIAL HEALTH EFFECTS	
Eye:	May cause eye irritation
Skin	May cause mild skin irritation
Ingestion	Large oral doses may cause irritation
Inhalation	Product as supplied is not hazardous. May cause serious health damage
	due to breating dust from buffing operation with this material
Chronic	Silicosis, Cancer
GHS Label requirements	
Pictogram	
Signal Word Danger	
Hazard Statement	
H372	Causes damage to lungs through repeated breathing of dusts
	resulting from buffing operations with this material
Precautionary Statements	
P260	Do not breath dusts from buffing operation with this material
P285	In case of inadequate ventilation, wear respiratory protection
P280	Wear portective gloves/protective clothing/eye protection/ face protection
P302+P352	If on Skin: Wash with soap and water
P305+P351	If in eyes: Wash cautiously with water for 15 minutes.
<b>3. COMPOSITION/INGRE</b>	DIENT INFORMATION

Ingredients	CAS	PEL/ TLV	Weight %
Tripoli; Silica	1371-95-9	0.1 mg/M3	60-75%
Fatty Acid /Glyceride		Not Hazardous	18-35%
Petroleum Oil or Wax		Not Hazardous	2-8%

4. FIRST AID MEASURES	
Inhalation	If exposed to excessive levels of dust, remove to fresh air.
	Get medical attention if cough, irritation or other symptoms develop.
Skin Contact	Wash with soap and water.
	Get medical attention if irritation or rash develop.
Eye Contact	Immediately flush eyes with plenty of water for 15 minutes.
	If abrasive particles are not removed, obtain medical attention.
Ingestion	Swallowing less than an ounce will not cause significant harm.
	For larger amounts do not induce vomiting,
	but give two 12 ounce glasses of water and obtain medical advice.
<b>5. FIRE FIGHTING MEASU</b>	IRES
Flash Point	>350 F
Extinguishing Media	Use alcohol foam, carbon dioxide, or dry chemical
	when fighting fires involving this material.
Fire fighting Procedure	Remove ignition source and fight fire as if it were a grease fire.
Special Protective Equipment	As in any fire, wear self contained breathing apparatus (pressure-demand,
	MSHA/NIOSH approved or equivalent) and full protective gear.
Hazardous Combustion	If heated to high temperature the product may emit carbon monoxide
Products	and carbon dioxide
6 ACCIDENTAL RELEASE I	MEASURES
Environmental Precautons	None known
Methods for Clean up	Sweep or Scoop up material for reuse or reclaim if possible,
	otherwise place in a disposal container for proper disposition.
7. HANDLING AND STOR	۵GF
Handling	No special handling requirements are known
nanunig	No special handling requirements are known
Storage	Keep out of sun and away from heat sources, as product may melt.
	Observe all safeguards for container residue until cleaned or destroyed.
	Do not flush to sewers or waterways unless authorized to do so
	by appropriate government official.
	· · · · · · · · · · · · · · · · · · ·

## 8. EXPOSURE CONTROLS/PERSONAL PROTECTION

Exposure Limit Values	0.1 mg/ M	3 as dust resulting from t	he buffing	
	operation	with this material	-	
Engineering Measures	Ventilatior	n to keep dust level at exp	oosure limits	
Hygiene Measures				
Respiratory Protection	Wear resp	iratory protection such as	s a dust mask	
Hand Protection	Wear glove	es		
Eye Protection	Wear safet	ty glasses with side shield	s or goggles	
Skin Protection	Wash with	soap and water before e	ating or after shi	ft
9. PHYSICAL AND CHEMIC	AL PROP	ERTIES		
Physical State	Solid	Solubility in Water	None	
Color	Brown	Flash Point	>350F	
Boiling Point	N/A	Vapor Density	N/A	
Melting Point	125 deg.F	Evaporation Rate	N/A	
Specific Gravity	> 1.1	Odor	Mild;	
рН	N/A	VOC	None	
Autoignition Temperature	N/A			

#### **10. STABILITY AND REACTIVITY**

10. STADILITT AND REACT	VIII		
Stability		Product is stable	
Conditions to Avoid		Material can ignite if exposed to a continuous flame or heat source	
Incompatible Materials	1	None known	
Hazardous Decomposition Produce	azardous Decomposition Products If product is involved in a fire, carbon monoxide could be em		be emitted
Hazardous Polymerization		Will Not occur	
11. TOXICOLOGICAL INFORMATION			
Evos	May cause i	irritation from abrasion	

Eyes	May cause irritation from abrasion.
Skin Contact	May cause irritation
Skin Absorption	Not likely
Inhalation	Dust from buffing operation includes silica which may cause silicosis, a lung disease. Silica is also found to cause lung cancer in humans.
Swallowing	No adverse effect is expected
<b>12. ECOLOGICAL INFORMA</b>	ATION
Ecological Information	No data available

#### Bioaccumulative Potential Bioaccumulation is unlikey

**Comments** This product is not believed to be toxic to aquatic life.

### **13. DISPOSAL CONSIDERATIONS**

GeneralIf discarded, the material in its original unused form is not a RCRA hazardous waste.Disposal should be in accordance with State and Local regulations for the<br/>disposal of non-hazardous waste. Be sure to check if compound (after used)

#### has come in contact with a hazardous substance before disposal

#### Packaging

Dispose in clean receptical or box.

14. TRANSPORTATION I	Not regulated		
Classificati	J J		
IMDG Classification	Not regulated		
ICAO Classification	Not regulated		
<b>15. REGULATORY INFOR</b>	RMATION		
UNITED STATES			
Sara Title III			
313 Reportable Ingredients	Contains silica		
302/304 Emergency Planning	None		
Emergency Plan	Report as required by the	state and local agencies	
	for both product and wast	-	
California Prop 65-		contains a chemical known to	the State of
	· · · · · ·	and/or reproductive harm.	
	Ingredient	Cancer	Reproductive
	Silica	Yes	No
<b>CERCLA (Comprehensive Resp</b>	onse, Compensation and Liab	iity Act)	
CERCLA	RQ None		
EPA HAZARD CATEGORIES			
	12 - product contains silica		
SARA 311/3	•		
SARA 311/3 TSCA (Toxic Substance Contro	•	e TSCA list	
SARA 311/3 TSCA (Toxic Substance Contro TSCA Stat	I Act) tus - All ingredients are on th	e TSCA list	
SARA 311/3 TSCA (Toxic Substance Contro TSCA Stat 16. OTHER INFORMATIC	I Act) tus - All ingredients are on th	e TSCA list	
SARA 311/3 TSCA (Toxic Substance Contro TSCA Stat 16. OTHER INFORMATIC Revision Number	<b>I Act)</b> tus - All ingredients are on th <b>DN</b> BA609-4	e TSCA list	
SARA 311/3 TSCA (Toxic Substance Contro TSCA Stat 16. OTHER INFORMATIC Revision Number	I Act) tus - All ingredients are on th DN	e TSCA list	
SARA 311/3 TSCA (Toxic Substance Contro TSCA Stat 16. OTHER INFORMATIC Revision Number Supersedes Date	<b>I Act)</b> tus - All ingredients are on th <b>DN</b> BA609-4	e TSCA list	
SARA 311/3 TSCA (Toxic Substance Contro TSCA Stat 16. OTHER INFORMATIC Revision Number Supersedes Date HMIS Rating	NI Act) tus - All ingredients are on th DN BA609-4 1/1/2014 1-1-0-0	e TSCA list brass, zinc and especially magnesium o	aluminum
SARA 311/3 TSCA (Toxic Substance Contro TSCA Stat 16. OTHER INFORMATIC Revision Number Supersedes Date HMIS Rating	Act) tus - All ingredients are on th DN BA609-4 1/1/2014 1-1-0-0 Metal Dusts from the buffing of		
SARA 311/3 TSCA (Toxic Substance Contro TSCA Stat 16. OTHER INFORMATIC Revision Number Supersedes Date HMIS Rating	Act) tus - All ingredients are on th DN BA609-4 1/1/2014 1-1-0-0 Metal Dusts from the buffing of along with buffing cloth fibers a	brass, zinc and especially magnesium o nd compound residues may cause fires	or explosions
SARA 311/3 TSCA (Toxic Substance Contro TSCA Stat 16. OTHER INFORMATIC Revision Number Supersedes Date HMIS Rating	Act) tus - All ingredients are on th DN BA609-4 1/1/2014 1-1-0-0 Metal Dusts from the buffing of along with buffing cloth fibers a when exposed to a strong ignition	brass, zinc and especially magnesium or nd compound residues may cause fires on source. These fires typically are starte	or explosions ed in the vent
SARA 311/3 TSCA (Toxic Substance Contro TSCA Stat 16. OTHER INFORMATIC Revision Number Supersedes Date HMIS Rating	Act) tus - All ingredients are on th DN BA609-4 1/1/2014 1-1-0-0 Metal Dusts from the buffing of along with buffing cloth fibers a when exposed to a strong ignitic pipes, collector bags or receptad	brass, zinc and especially magnesium or nd compound residues may cause fires on source. These fires typically are starte les used in waste gathering from the bu	or explosions ed in the vent ffing
SARA 311/3 TSCA (Toxic Substance Contro TSCA Stat 16. OTHER INFORMATIC Revision Number Supersedes Date HMIS Rating	Act) tus - All ingredients are on th DN BA609-4 1/1/2014 1-1-0-0 Metal Dusts from the buffing of along with buffing cloth fibers a when exposed to a strong ignitic pipes, collector bags or receptad ventilation system. Make sure th	brass, zinc and especially magnesium of nd compound residues may cause fires on source. These fires typically are starte les used in waste gathering from the bu nat the collectors are changed frequentl	or explosions ed in the vent ffing y and the
SARA 311/3 TSCA (Toxic Substance Contro TSCA Stat 16. OTHER INFORMATIC Revision Number Supersedes Date HMIS Rating	Act) tus - All ingredients are on the DN BA609-4 1/1/2014 1-1-0-0 Metal Dusts from the buffing of along with buffing cloth fibers a when exposed to a strong ignition pipes, collector bags or receptador ventilation system. Make sure the waste kept in a cool, dry environ	brass, zinc and especially magnesium or nd compound residues may cause fires on source. These fires typically are starte eles used in waste gathering from the bu nat the collectors are changed frequentl iment that is free from sparks or other s	or explosions ed in the vent ffing y and the trong ignition
SARA 311/3 TSCA (Toxic Substance Contro TSCA Stat 16. OTHER INFORMATIC Revision Number Supersedes Date HMIS Rating	Act) tus - All ingredients are on the DN BA609-4 1/1/2014 1-1-0-0 Metal Dusts from the buffing of along with buffing cloth fibers a when exposed to a strong ignition pipes, collector bags or receptant ventilation system. Make sure the waste kept in a cool, dry enviror sources. The collection devices a	brass, zinc and especially magnesium or nd compound residues may cause fires on source. These fires typically are started les used in waste gathering from the bu nat the collectors are changed frequentl ment that is free from sparks or other s hould be grounded to minimize static c	or explosions ed in the vent ffing y and the strong ignition harges.Dust
SARA 311/3 TSCA (Toxic Substance Contro TSCA Stat 16. OTHER INFORMATIC Revision Number Supersedes Date HMIS Rating	Act) tus - All ingredients are on the DN BA609-4 1/1/2014 1-1-0-0 Metal Dusts from the buffing of along with buffing cloth fibers a when exposed to a strong ignition pipes, collector bags or receptador ventilation system. Make sure the waste kept in a cool, dry enviror sources. The collection devices a collection receptacles should be	brass, zinc and especially magnesium or nd compound residues may cause fires on source. These fires typically are starte les used in waste gathering from the bu nat the collectors are changed frequent iment that is free from sparks or other s hould be grounded to minimize static cl designed by engineers who are familiar	or explosions ed in the vent ffing y and the trong ignition harges.Dust
SARA 311/3 TSCA (Toxic Substance Contro TSCA Stat 16. OTHER INFORMATIC	Act) tus - All ingredients are on the DN BA609-4 1/1/2014 1-1-0-0 Metal Dusts from the buffing of along with buffing cloth fibers a when exposed to a strong ignition pipes, collector bags or receptad ventilation system. Make sure the waste kept in a cool, dry enviror sources. The collection devices as collection receptacles should be potential hazard of a flammable	brass, zinc and especially magnesium or nd compound residues may cause fires on source. These fires typically are started les used in waste gathering from the bu nat the collectors are changed frequentl ment that is free from sparks or other s hould be grounded to minimize static c	or explosions ed in the vent ffing y and the strong ignition harges.Dust with the fight the fire